Er. J. VARA PRASAD

BE., PGDCM., C. ENG. (i), FIV

MICA, MIE, M.I.STRUCT.E

CHARTERED ENGINEER,

APPROVED ENGINEER BY P.W.D & N COLLECTOR'S PANEL

TO ISSUE BUILDING STRUCTURAL STABILITY CERTIFICATE

Belly Area,

283/35, 2<sup>nd</sup> Floor, Jai Hind Flats

Anna Nagar (West),

Chennai - 600 040.

Office No.044 26260799

CELL: 94433 79267, 99623 99199

Email:jvprasaad@gmail.com

## STATEMENT ACCOMPANYING FORM 'A'

Name of the School

 $\sim$ 

Location (Street No. Ward No . . Survey No.197/2B Part, 197/2C, Town Survey No.7/5 Part,

ABS VIDHYA MANDHIR

Name of place (i.e.) corporation Ward No.A, Block No.21, Thalakanchery Road

Municipality /Panchayath ) Aiveli Agaram, Thiruvallur – 602 001

ώ Year of construction

••

**BLOCK NO.1** • • RCC: <u>(</u> щ , F. F, S. TI.  $\infty$ ;-; -:-: **2010** (About 9 Years)

**BLOCK NO.2** •• RCC: G. F, F. F & S. F - 2016 (About 3 Years)

4 Purpose for which the building is . . For conducting School Classes

being used or proposed to be used

Purpose for which the building has . . For conducting School Classes

hitherto been used

Ş

ġ Details of construction of the building

(particulars) of the foundation, soil

specification of the various parts as under

Ö

Basement

Foundation

Superstructure RCC Framed Structures, 9" thick walls using CM

RCC Plinth Beam, Brick Work in CM

RCC Isolated Footing, RCC Grade Beam

Floor & Roof, are to be given .. .. Roof – RCC, Flooring – Ceramic Tiles & Vitrified Tiles

7. Period for which license is required . . From 15.06.2019 to 14.06.2022

FOR THREE YEARS ONLY

No. of persons to be accommodated: About 3200 Pupils

 $\infty$ 

(Three Thousand Two Hundred Pupils Only)

Place : Chennai

Dated: 07.05.2019

PODDM, CENG/FIV, ME, RICA, MI Struct E, Charlered Engineer in Callector's Planet, Competent Person to acus Stability Certificate No. 283/35, 2nd Floor, Jist Hill Flore, Bolly Area, Nr. Channet, a School, Anna Nagur West, Channet 60/y Area N Anna Nagor 78 Call 1980277

#### FORM - B

# STATEMENT TO ACCOMPANY THE REPORT OF STRUCTURAL SOUNDNESS

Location of the	Age of	No of	Short Description, of structure
Building door	the	Storeys	steel RCC Framed or Load Bearing
No. Street Name	Building		Masonry
& Name of the Place.			
ABS VIDHYA MANDHIR			RCC Isolated Footing, RCC Grade Beam
Survey No.197/2B Part, 197/2C, Town Survey No.7/5 Part,	//2C, Town Survey No.7	/5 Part,	Plinth Beam, Brick Work in CM
Ward No.A, Block No.21, Thalakanchery Road,	nalakanchery Road,		RCC Columns, 9" thick walls using CM
Aiveli Agaram, Thiruvallur – 602 001.	- 602 001.		Roof – RCC , Flooring – Ceramic Tiles &

BLOCK NO.2	BLOCK NO.1
••	••
RCC: G. F, F. F & S. F – 2016 (About 3 Years)	RCC: G. F, F. F, S. F & T. F - 2010 (About 9 Years)

Vitrified Tiles

School Classes	For conducting	To be used	The building is	Purpose for which
FOR THREE YEARS ONLY	15.06.2019 to 14.06.2022	is required	for which the license	period
(Three Thousand Two Hundred Pupils	About 3200 Pupils.	accommodated.	persons	No. of
o Hundred Pupils Only )	The Building is Structurally Sound			Remarks

This

does

not include

wiring / Gadgets has to be checked properly and to be maintained periodically. All Necessary safety standards responsible. Structural Alteration in the premises and should be trained for operation. If any fire accident / Mishap occurs we are not held Eventualities caused by Natural Calamities. We here by advise that the Periodical Repairs and Renovations Shall not held responsible and this Report gets cancelled. Further this Report covers the above said Building Blocks has to be Strictly adhered. If any violations is found at a later period after issue of this Report / License we are Permission from the Competent Authority. Emergency Exit to be provided as per norms. All electrical points, Only. Legal Aspects were not considered in this report. carried out to the Entire Building Block regularly. Further Necessary firefighting equipment's should be kept / Deviation Should Not be Carried out to a part / whole Building without Prior Report any

Place Chennai

Dated ٠. 07.05.2019

J. VARAMINASAO
PODOM, Cleng, FIV. ME. MCA. MA Smot E.,
Ch...rieved Engineer
Approved Engineer in Collector's Panel,
Competent Person to Jusus Stability Certificate
No. 283/35, 2nd Floor, Jol Mod Plats,
Bally Area, Nr. Chimneya School
Anna Magar West, Cherriai - 600 040.
Cell: 996/23 93/99, Ph. 044 26/26 0799

### FORM - C

Form of Report of structural soundness under sub-section (4) of section 4 of

The Tamil Nadu public (Licensing) Rules, 1966 Tamil Nadu public building (licensing) Act 1965 (Tamil Nadu act 1 of 1965) Referred to in rule 4 of the

salient technical features: We have inspected the building on 19.06.2017, mentioned in the statement and furnish below its

Foundation:

ω Depth below ground level

About 1.82 Mts.

Ö Nature of soil met with at

foundation level. Clay Soil

Ü Pressure at foundation

<u>a</u> Probable safe bearing capacity of

The soil strata met with at foundation About 20T / Sq. M

2 Superstructure

ည Minimum stress in the most Brick Work in cm mix

Critical section of 18Mt / Sq.cm

Masonry and concrete

0 Nature of masonry and concrete **Brick Masonry** 

And its safe permissible stress

We are of the Opinion that the building is structurally sound. A license can be granted for the period

from 15.06.2019 to 14.06.2022 (FOR THREE YEARS ONLY)

Place Chennai

Date 07.05.2019

ollector's Panel, Certificate

J. VARY ASAM
PGOCM., C.Eng., Pfv., Mrs., Mic., M

Er. J. VARA PRASAD

BE., PGDCM., C. ENG. (i), FIV

MICA, MIE, M.I.STRUCT.E

CHARTERED ENGINEER,

APPROVED ENGINEER BY P.W.D & N COLLECTOR'S PANEL

TO ISSUE BUILDING STRUCTURAL STABILITY CERTIFICATE

283/35, 2<sup>nd</sup> Floor, Jai Hind Flats

Belly Area,

Anna Nagar (West),

Chennai - 600 040.

CELL: 94433 79267, 99623 99199

Office No.044 26260799

Email:jvprasaad@gmail.com

### ANNEXURE TO "STATEMENT ACCOMPANYING FORM - A"

as Compound wall, Semi / Non permanent structures either in GF and any other floors and etc., We here by the above mentioned building Block/ Floors only and does not include any other Buildings or Structures Such (About 9 Years) / BLOCK NO.2: RCC: G. F, F. F & S. F — 2016 (About 3 Years), are available. This Report covers Agaram, Thiruvallur - 602 001. The Following Building is of BLOCK NO.1: RCC: G. F, F. F, No.197/2B advise that the Periodical Repairs and Renovations Shall be carried out to the Entire Building Block regularly. Part, 197/2C, Town Survey No.7/5 Part, have inspected the School Premises Buildings, ABS VIDHYA MANDHIR, Ward No.A, Block No.21, Thalakanchery Road, Located at S. F & T. F Survey Aiveli 2010

Gadgets has to be checked properly and to be maintained regularly. Periodic water proofing treatment is to be per norms. Structural Alteration / Deviation Should Not be carried out to any of the blocks for Whole Building operation. If any fire accident / Mishap occurs we are not held responsible. Emergency exit to be provided as Inspection Chamber, septic Tank Openings Boards/Main Switches / cables, Generator, Electrical Maintenance Room has to be kept in safety with lock under construction. Any Further additional construction either in F.F or in any other Floors / Blocks the key position. Access to open terraces to be kept in Lock & key Position. The UG sump, manholes, OHT, any Part of Building without Prior Permission from the Competent Authority. All Electrical points, wiring / as per standards. found violated at a later date after Further Necessary firefighting equipment's should be kept in the premises and should be trained for gets cancelled. approvals / structural design / stability has to be subsequently obtained. All Electrical Panel Legal Aspects were This Report does not cover any Structure / Partly completed Structure or building not considered in this report. issue of this Report / License as to be Sealed with cover slab. If any above we are not held responsible and this mentioned Aspects

Place • • Chennai

Date 07.05.2019

PODOM, O.S.M. FIV. MIE. NO. Ohunered Enginee Struct E.

Approved Engineer in Collector's Panel, Competent Person to leave Stability Certification, No. 283/35, 2nd Place, Juli Hind Flats, Belly Area, Nr. Onlineaya School, Juli N. Chinnaya School )edifficate

Amna Nager West, Ch Cell : 93623 99199 78583

Chenna